

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	35	fuse same transformer same current with sensor same (indicator or signal\$5 or alert or alarm)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 14:32
L2	11	340/638.ccls. and fuse same (current near6 sensor)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:04
L3	480	fuse with cutout	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:23
L4	2	3 and current with sensor same (indicator or alert or alarm)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:20
L5	10	3 and current with sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:20
L6	2	fuse with cutout same (current near9 (sensor or detector))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:27
L7	32	337/171,172.ccls. and fuse with cutout	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:32
L8	2	337/171,172.ccls. and current with sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:51
L9	0	337/171,172.ccls. and current with sensor with cutout	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:36
L10	2	current with sensor with fuse with cutout	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:37
L11	36	340/638.ccls. and current with sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:53

L12	11	340/638.ccls. and current with sensor with fuse	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:57
L13	1	340/638.ccls. and current with sensor with fuse with cutout	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 15:57
L14	2	current with sensor with fuse with cutout	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 16:08
L15	458	324/457.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 16:09
L16	397	fuse with blown same indicator	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 16:10
L17	1	fuse with blown same indicator same current with sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/10 16:11